





# HANNU 40




ø 5 mm






6x140 mm



# TEPNE







# HANNU 40




Ø 3 mm



4x40 mm







GU









# HANNU 40




# HANNU 40




# HANNU 40











Ø 5 mm




6x140 mm



# HANNU 40















# HANNU 40



# HANNU 40



# HANNU 40





4x50 mm





# HANNU 40





EX17

A

A

# HANNU 40











4x50 mm






# HANNU 40



# HANNU 40



4x40 mm



# HANNU 40

